








## Harting

| Han 10 E<br>16 + $\frac{5}{2}$ | Screw Terminal  |       |  | Gland | Top Entry Hood<br>2 levers on the Housing<br> | Gland | Panel Mount Housing<br>2 levers on the Housing<br> | Surface Mount Housing<br>2 levers on the Housing<br> | Two Side-Entry<br>2 levers on the Housing<br> | Gland | Gland |
|--------------------------------|-----------------|-------|--|-------|--|-------|--|---|--|-------|-------|
|                                | Working Voltage | 380V  |  |       |  |       |  |   |  |       |       |
|                                | Working Current | 16A   |  |       |  |       |  |   |  |       |       |
|                                | Wire Gauge      | 2,5mm |  |       |  |       |  |   |  |       |       |
|                                |                 |       |  | 20mm  | L 19 30 010 1420   | 20mm  | 09 30 010 0301   | L 19 30 010 1230  | L 19 30 010 1270   | 20mm  | A20   |
|                                |                 |       |  | 25mm  | H 19 30 010 1421   | 25mm  |  | L 19 30 010 1231  | L 19 30 010 0271   | 25mm  | A22   |
|                                |                 |       |  | 32mm  | H 19 30 010 0427   | 32mm  |  | H 19 30 010 0231  | L 19 30 010 0272   | 25mm  | A23   |

| Han 16 E<br>16 + $\frac{5}{2}$ | Screw Terminal  |       |  | Gland | Top Entry Hood<br>1 lever on the Housing<br> | Gland | Panel Mount Housing<br>1 lever on the Housing<br> | Surface Mount Housing<br>1 lever on the Housing<br> | Two Side-Entry<br>1 lever on the Housing<br> | Gland | Gland |
|--------------------------------|-----------------|-------|--|-------|--|-------|---|---|--|-------|-------|
|                                | Working Voltage | 380V  |  |       |  |       |   |   |  |       |       |
|                                | Working Current | 16A   |  |       |  |       |   |   |  |       |       |
|                                | Wire Gauge      | 2,5mm |  |       |  |       |   |   |  |       |       |
|                                |                 |       |  | 25mm  | L 19 30 016 1441   | 25mm  | 09 30 016 0307  | 19 30 016 1251  | 19 30 016 1291   | 25mm  | A22   |
|                                |                 |       |  | 32mm  | H 19 30 016 1442   | 32mm  | with thermoplastic cover<br>09 30 016 0306  | with thermoplastic cover<br>19 30 016 1256  | with thermoplastic cover<br>19 30 016 1296   | 25mm  | A22   |
|                                |                 |       |  | 32mm  | H 19 30 016 0447   | 32mm  |   |   |  |       |       |

L = Low Construction H = High Construction

## Harting

| Han 16 E<br>16 + $\frac{+}{-}$ | Screw Terminal |  |  | Side Entry Hood   | Gland                | Top Entry Hood  | Gland                | Panel Mount Housing  | Surface Mount Housing   | Gland        | Two Side-Entry  | Gland             |
|--------------------------------|----------------|--|--|---|----------------------|---|----------------------|--|---|--------------|---|-------------------|
| Working Voltage                | 380V           |  |  | 2 levers on the Housing   |                      | 2 levers on the Housing   |                      | 2 levers on the Housing  | 2 levers on the Housing   |              | 2 levers on the Housing   |                   |
| Working Current                | 16A            |  |  |  |                      |  |                      |  |  |              |  |                   |
| Wire Gauge                     | 2,5mm          |  |  | L 19 30 016 1521<br>H 19 30 016 1522<br>H 19 30 016 0527                            | 25mm<br>32mm<br>32mm | L 19 30 016 1421<br>H 19 30 016 0427<br>H 19 30 016 0428                            | 25mm<br>32mm<br>40mm | 09 30 016 0301   | L 19 30 016 1231<br>L 19 30 016 0232  | 25mm<br>32mm | L 19 30 016 1271<br>H 19 30 016 0271<br>H 19 30 016 0272                          | A22<br>A22<br>A23 |

| Han 24 E<br>24 + $\frac{+}{-}$ | Screw Terminal |  |  | Side Entry Hood  | Gland                | Top Entry Hood   | Gland        | Panel Mount Housing   | Surface Mount Housing  | Gland        | Two Side-Entry   | Gland                   |
|--------------------------------|----------------|--|--|--|----------------------|--|--------------|---|--|--------------|--|-------------------------|
| Working Voltage                | 380V           |  |  | 1 lever on the Housing   |                      | 1 lever on the Housing   |              | 1 lever on the Housing  | 1 lever on the Housing   |              | 1 lever on the Housing   |                         |
| Working Current                | 16A            |  |  |  |                      |  |              |  |  |              |  |                         |
| Wire Gauge                     | 2,5mm          |  |  | L 19 30 024 1541<br>L 19 30 024 1542<br>H 19 30 024 0547                             | 25mm<br>32mm<br>32mm | L 19 30 024 1442<br>H 19 30 024 0447   | 32mm<br>32mm | 09 30 024 0307<br>with thermoplastic cover<br>09 30 024 0304                        | 19 30 024 1251<br>with thermoplastic cover<br>19 30 024 1256                       | 25mm<br>25mm | 19 30 024 0292<br>with thermoplastic cover<br>19 30 024 1296                       | A23<br>2x32mm<br>2x32mm |

L = Low Construction H = High Construction

## Harting

| Han 24 E<br>24 + $\frac{5}{5}$ | 380V  |  | Screw Terminal | Side Entry Hood<br>2 levers on the Housing<br> | Gland | Top Entry Hood<br>2 levers on the Housing<br> | Panel Mount Housing<br>2 levers on the Housing<br> | Surface Mount Housing<br>2 levers on the Housing<br> | Two Side-Entry<br>2 levers on the Housing<br> | Gland | Gland  | Gland |
|--------------------------------|-------|--|----------------|---|-------|--|--|---|--|-------|--------|-------|
|                                | 16A   |  |                |   |       |  |  |   |  |       |        |       |
|                                | 2,5mm |  |                |   |       |  |  |   |  |       |        |       |
|                                |       |  |                |   |       |  |  |   |  |       |        |       |
|                                |       |  |                | L 19 30 024 1521  | 25mm  | L 19 30 024 1422   | 09 30 024 0301   | L 19 30 024 1231  | L 19 30 024 1271   | 25mm  | 2x25mm | A22   |
|                                |       |  |                | L 19 30 024 1522  | 32mm  | H 19 30 024 0427   |  | L 19 30 024 0232  | H 19 30 024 0272   | 32mm  | 2x32mm | A21   |
|                                |       |  |                | H 19 30 024 0527  | 32mm  | H 19 30 024 0428   |  |   |  | 32mm  |        | A23   |
|                                |       |  |                |   | 40mm  |  |  |   |  |       |        |       |

L = Low Construction H = High Construction